

TARONJA SCHOOL BUILDING RISK ASSASSMENT.

Heath & Safety Analysis – Taronja Valencia, Spain

Important

The information contained here is provided as a support to any investigations the school wishes to undertake, prior to the group's departure. Representatives of the school should personally satisfy themselves as to the ultimate suitability of the destination, in terms of risks to the health, safety and general wellbeing of the group. We strongly urge group leaders to conduct an exploratory visit, so that they have a personal awareness of the location and are familiarized.

Health & Safety generally comes down to the use of common sense, to predict potential risks to health and safety, and to consider options to minimize, control and prevent such risks. It is important for group leaders to consider this document carefully, and establish contingency plans where feasible, based on their knowledge of the group, and the group's intentions.

Attitudes to risk management, safety procedures and legislation vary substantially from country to country. It is the duty of group leaders to familiarize themselves with these important differences.

If you have any questions, or if you wish to discuss any other issues you feel are pertinent to the correct preparation of your trip, please contact us so that we can help you further.

Email: grupos@taronjaschool.com

School building - Risk assessment

1. Building Type

What is the basic structure & material of the building? The building is made of concrete.

How old if the building and what is its state of repair? The building was built in 1963 and completely reformed in 2022.

How many Floors are there? 3 floors

2. Fire Prevention

Is there evidence of combustible material anywhere? No

Do plugs, wiring, sockets appear to be in good condition? Very good conditions

Calle Garcilaso 15 B | 46003 Valencia-España | www.taronjaschool.com | info@taronjaschool.com







Miembro de



Are corridors/landing/stairs kept clear of obstructions? Yes

Is there 24 hour staffing at the property/residence by staff who will be actively on duty? Yes

3. Fire Warning

Is there a fire alarm fitted, and how is it activated? Yes, we have all the school well equipped with an electronic fire alarms.

Are smoke / heat detectors fitted in corridors, bedrooms, stairs and public rooms? No

If free-standing, how are students alerted by a fire alarm? At the first sign receptionist would be alerted and we start the students evacuation according to our emergency exit plan.

Is alarm linked directly to the fire service? No

If not, how are the fire service notified? The receptionist calls the fire service immediately.

4. Fire: Means of Escape

Are there adequate stairways? Yes

Do all escape routes lead to safety? Yes

Are escape routes fitted with fire doors or partitions to stop the spread of fire and smoke? Yes

Are escape routes properly marked and unobstructed? Yes

Is there working emergency lighting? Yes

Are clear evacuation plans on the back of every classroom door? Yes

Is there a designated and marked fire assembly point? Yes

5. Fire Fighting

Are fire extinguishers present? Yes

Are hose reels present? No

Does fire fighting equipment appear to be adequately maintained? yYes

Calle Garcilaso 15 B | 46003 Valencia-España | www.taronjaschool.com | info@taronjaschool.com







Miembro de:



6. General Safety

- Is the lighting in the building generally adequate? Yes
- Is Air recycling available? Yes
- Is air-conditioning available? Yes

7. Balconies

Are there any balconies? Yes, but they have a protective railing.

8. Grounds

Are any grounds tidy and free from obvious risks? Yes

9.Sourronding.

Does the guest entrance open onto a major road? No, it is open on a Pedestrian street

Valencia 1 febrero 2023

Eva Batalla Alonso

(Manager) Escuela Taronja



CIF: B97457600 C./ Garcilaso 15-B 46003 Valencia (España)

Calle Garcilaso 15 B | 46003 Valencia-España | www.taronjaschool.com | info@taronjaschool.com







Acreditado por

Miembro de: